

# General Environmental Incident Summary

**Incident:** 3679      **Date/Time Notice:** 3/10/2015      1630      **DEM Incident No:**  
**Responsible Party:** Dakota Midland Grain  
**Date Incident:** 3/10/2015      **Time Incident:** 15.00      **Duration:** 10 minutes  
**County:** McHenry      **Twp:** 152      **Rng:** 79      **Sec:** 6      **Qtr:**  
**Lat:** 48.01936      **Long:** -100.84780      **Method:** Interpolation from map  
**Location Description:** Dakota Midland Grain, highway 52 west Voltaire ND

**Submitted By:** Tom Bass      **Affiliation:**  
**Address:** 1219 hwy 52 west  
**City:** voltaire      **State:** ND      **Zip:**

**Received By:**

**Contact Person:**

1219 hwy 52 west  
voltaire, ND

**Distance Nearest Occupied Building:** 10 Feet      **Release Contained:** Yes

**Type of Incident:** Tank Leak

**Description of Released Contaminant:** Diesel Fuel

**Volume Spilled:** 10.00 gallons

**Ag Related:** Yes

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

Truck diesel fuel tank line came apart

**Risk Evaluation:**

none

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

oil dry

**Wastes Disposal Location:**

**Agencies Involved:**

## ***Updates***

---

***Date:*** 3/11/2015

***Status:*** Reviewed; No Followup Required

***Staff:*** O'Gorman, Brian

***Updated Volume:***

***Notes:***

Spoke with the responsible party via phone at 16:45. Responsible party indicated that they had put Floor Dry on areas that were not permeable surfaces and had hand shoveled areas of saturation on gravel surface. The Floor Dry and surface materials were placed into a 55-gallon drum and were to be transported to the Sawyer landfill. No further followup required.